

Electrical Equipment

AD/ELECT/20

**Eisemann Magneto Coils
P/N H27-958 - Inspection and Replacement**

5/69

Applicability: All Eisemann magnetos type AM-4, AM-6, LA-4 and LA-6 installed on, but not necessarily limited to, the following engines:

Continental A-50, A-65, A-75, A-80, C-75, C-85, C-115, C-125, E-165 and E-185 series.

Franklin (Aircooled) 2A4, 4AC, 4A4, 6AC, 6AL, 6A8, 6A4, 6V4, 6AG4 series.

Menasco C4, D4, D4-87 series.

- Requirement:**
1. Inspect coils P/N H27-958 for a yellow inspection stamp consisting of a letter and numeral.
 2. Remove from further service those coils bearing the following yellow stamps:
A76, B76, C76, D76, F76, G76, H76, J76, K76, L76, M76, D86, E86, F86, G86, H86, J86, K86.
 3. Install coils P/N H27-958 bearing yellow inspection stamps other than those listed under 2.

Compliance: Within 35 hours time in service after 16 May 1969.