



## MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved  
OMB No. 2120-0020  
11/30/2007

Electronic Tracking Number

For FAA Use Only

*NM07-SLC-FSDO*

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$1,000 for each such violation (Section 901 Federal Aviation Act 1958)

<b>1. Aircraft</b>	Nationality and Registration Mark <b>N3576T</b>	Serial No. <b>F-042</b>	
	Make <b>TAYLORCRAFT</b>	Model <b>F19</b>	Series
<b>2. Owner</b>	Name (As shown on registration certificate) <b>RANWEILER, JOHN L</b>		Address (As shown on registration certificate) Address <b>P.O. BOX 2118</b>
			City <b>EL PRADO</b> State <b>NM</b> Zip <b>87529-2118</b> Country <b>U.S.A</b>

**3. For FAA Use Only**

The technical data identified herein has been found to comply with applicable airworthiness requirements and is hereby approved for use only on the above described aircraft, subject to conformity inspection by a person in § 43.7.

*David C. [Signature]*      *12/23/2009*  
Inspector, NM-FSDO-07      Date

4. Type		5. Unit Identification			
Repair	Alteration	Unit	Make	Model	Serial Number
<input type="checkbox"/>	<input checked="" type="checkbox"/>	AIRFRAME		(As described in Item 1 above)	
<input type="checkbox"/>	<input type="checkbox"/>	POWERPLANT			
<input type="checkbox"/>	<input type="checkbox"/>	PROPELLER			
<input type="checkbox"/>	<input type="checkbox"/>	APPLIANCE	Type		
			Manufacturer		

**6. Conformity Statement**

<b>A. Agency's Name and Address</b> Name <b>Timothy Popp</b> Address <b>415 Highland Dr.</b> City <b>Riverdale</b> State <b>UT</b> Zip <b>84405</b> Country <b>U.S.A.</b>	<b>B. Kind of Agency</b> <input checked="" type="checkbox"/> U.S. Certificated Mechanic <input type="checkbox"/> Manufacturer <input type="checkbox"/> Foreign Certificated Mechanic      C. Certificate No. <input type="checkbox"/> Certificated Repair Station <b>393705201</b> <input type="checkbox"/> Certificated Maintenance Organization
---	---

D. I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.

Extended range fuel per 14 CFR Part 43 App. B <input type="checkbox"/>	Signature/Date of Authorized Individual
--	---

**7. Approval for Return to Service**

Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is     **APPROVED**     **REJECTED**

<b>BY</b>	FAA Fit Standards Inspector	Manufacturer	Maintenance Organization	Person Approved by Canadian Department of Transport
	FAA Designee	Repair Station	<input checked="" type="checkbox"/> Inspection Authorization	Other (Specify)

Certificate or Designation No. <b>393705201</b>	Signature/Date of Authorized Individual
--	---

## NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

### 8. Description of Work Accomplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N3576T

4 Sept 2009

Nationality and Registration Mark

Date

- 1) Removed Taylorcraft Wire from stamped wing ribs during wing recover.
- 2) Replaced Taylorcraft wire with Rib Lacing IAW AC43.13-1B chapter 2 (Fabric Covering) to secure fabric to wings because of the lack of availability of Taylorcraft wire and to eliminate damage to wing ribs during the removal and installation of wire.
- 3) This installation is similar to Piper PA18-90 wing fabric installation.
- 4) Wing loading is the same as Piper PA18-90 for a wing span of 36' and wing chord of 63" and the number of ribs (15) per wing at 1500LBS gross weight and a never exceed speed of less than 150 MPH (AC43.13-1B fig 2-12.)
- 5) New fabric installed I.A.W. Poly Fiber Installation manual and STC SA1008WE except for deviation stated above.

#### Instructions for Continued Airworthiness

1. **Introduction:** Replace Taylorcraft wire with Rib Lacing for wing fabric recovering.
2. **Description:** Removal of wing Taylorcraft wire and replace it with rib lacing IAW AC43.13-1B.
3. **Control:** N/A
4. **Service Information:** N/A
5. **Maintenance Instructions:** Per AC43.13-1B Chapter 2 (Fabric Installation).
6. **Troubleshooting:** N/A
7. **Removal and Replacement information:** Per AC43.13-1B Chapter 2 (Fabric Installation) and Poly Fiber installation Manual.
8. **Diagrams:** N/A
9. **Special Inspection Requirements:** N/A
10. **Application of Protective Treatments:** N/A
11. **Data:** Piper N/A
12. **List of Special Tools:** Rib Lacing Needle
13. **For Commuter Category Aircraft:** N/A
14. **Recommended Overhaul Periods:** N/A
15. **Airworthiness Limitations:** N/A
16. **Revision:** A letter will be submitted to the local FSDO with a copy of the revised FAA Form 337 and revised ICA. The FAA inspector accepts the change by signing Block 3 and including the following statement: "The attached revised/new Instructions for Continued Airworthiness (date ) for the above aircraft or component major alteration have been accepted by the FAA, superseding the Instructions for Continued Airworthiness (date )." Once the revision has been accepted, a maintenance record entry will be made, identifying the revision, its location, date of the Form 337.

**Comments:**

DC2 12/23/09



# Federal Aviation Administration

---

## Memorandum

Date: November 27, 2009

From : Manager, Denver Aircraft Certification Office, ANM-100D

To: Manager, Salt Lake City Flight Standards District Office

*Roger Caldwell*  
FOR: TODD DIXON

Attn: David C. Longan

Prepared by: Roger Caldwell, Denver Aircraft Certification Office, ANM-100D  
Phone: (303) 342-1086

Subject: ACTION: Alternate means of attaching fabric to wings of Taylorcraft F19

---

In response to your memo dated October 15, 2009 for coordination concerning the structural analysis of the ribs pertaining to an alternate means of attaching fabric to the wings of N3576T, a 1975 Taylorcraft F19 S/N: F-042 in which rib lacing would be used as opposed to the original wire clips fasteners.

We are in concurrence with this installation process and we strongly advise that the wing recover method be strictly adhered to IAW the Poly Fiber manual, STC SA1008WE, and AC 43-13-1B (Chapter 2, Section 1, Fabric Covering and Figure 2-6), as any deviations could degrade the quality and integrity of the structural load distribution.

If you have any questions please contact Roger Caldwell at (303) 342-1086.