NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8.	Description	of Work	Accomp	lished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

USA, N3572T, 20 JANUARY 1999

1. Installation of rivets in wing ribs to hold fabric.

1.	installation of fives in wing fibs to hold labric				
	 A. While installing new fabric on wings, installed 1/8 inch Marson rivets (P# AB4-4) into wing ribs to hold fabric onto wing ribs. B. This replaces original Martin (Univair P# PC 399) rib stitching wire used by Taylorcraft. C. Installation and inspection procedures are the same as Bellanca Citabria 7ECA aircraft per maintenance manual section 11 and parts manual figure 34. D. Weight and balance updated as required. 				

		The second secon			
		4			
		8			
		1			
	Additional Sheets are Attached	150			