UNIVERSAL AIRCRAFT INDUSTRIES

Field, Offices and Warehouses: Sky Ranch Airport POST OFFICE BOX 5306 • DENVER 17, COLORADO Telephone: 364-9151

February 19, 1962

Ben's Aircraft Service P.O. Box 227 Municipal Airport Waterloo, Iowa ·

NIVAIR

Gentlemen:

In answer to your letter of February 12, I am enclosing several sheets which outline the changes which must be made on the BC12D to put in the 85H.P. Continental engine.

I am sorry we do not have the longer engine mount or the cowling. We do not even have blueprints for this. During the time the Taylorcraft program was so disorganized, back in Conway, Pennsylvania, it appears that anyone who wanted to just helped themselves to any engineering and prints that they wanted. We therefore, did not receive a lot of this material. I regret that we cannot be of more help to you in this matter.

Yours very truly,

UNIVERSAL AIRCRAFT INDUSTRIES

Frank A. King

Parts Manager

FAK/rc

FAA Repair Station No. 3846 --- Airframe, Class 1 and 3 unlimited; Power Plant, Class 1 unlimited; Propellers limited to Beech, Hartzell, Sensenich, McCauley, Hamilton Std. and Koppers NEW AND USED PARTS FOR NEARLY EVERY MAKE OR MODEL