NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

| 8. | Description of Work Accomplished (If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.) |
|----|---|
| | Installed Bendix/King KY-97A VHF Communications Transceiver (wt. 2.8 lbs. sta. 0.0), and Comat CI-121 antenna (wt. 0.5 lbs. sta. 58.0). Manufactures racks and specifications were used (Installation Manual p/n 006-00674-0003 Rev. 3 dated April 1994), and Avionics Specialists of Alaska, Inc. drawing # D:\\27440\KY97-A.001 dated 13 January 1997 as installation data. |
| | Weight and balance change has been calculated and entered in the aircraft records. Electrical load is within 80% of limit. |
| | All work was done in accordance with current FAA regulations and AC 43.13-1A Chapter 11 Section 2,3,4,5, and 7; Chapter 13; Chapter 15 Sections 1, and 2; AC 43.13-2A Chapters 2 and 3. XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

☐ Additional Sheets Are Attached